Er. Vikas Gupta

B.Tech.(IT-BHU), M.I.E., F.I.V. F-17437 M-13094618 CAT 15-A-2006

Ref:

GUPTA CONSULTANTS

Engineers-Architects-Approved Valuers Structural Designers Vaastu Consultants-Interior Designers

Dated: 31.03.2022

TO WHOMSOEVER IT MAY CONCERN

This is to certify that the land measuring 59780.66 Sqm located at Hapur Road, Modinagar, belongs to Dayawati Modi Public School, Modinagar which is a A Unit of Daya Charitable Trust New Delhi. Detailed survey plan of land is attached.

Applicant:

Manager Dayawati Modi Public School Modinagar, (A Unit of Daya Charitable Trust New Delhi.)

Engineer:

VIKAS GUPTA

B Tech. (Civil)

IIT-BHU(1993),MIE B. Tech. (Civil), M.I.E., F.I.V. M-130949-8 F-17437

CAT 15-A-2006 UPOBIPAS Reg. No. M1309468/06062018 Structural Designer & Govt. Approved Valuer

Mobile: 09837184019 Off: 107-108, Satyam Plaza Complex, P L Sharma Road, Meerut. Ph 0121-4003483 E-mail: consultantsgupta@yahoo.co.in

Resi: C-81, Pallav Puram, Phase I, Meerut. Ph 0121-2577473

Er. Vikas Gupta

B.Tech.(IT-BHU), M.I.E., F.I.V. F-17437 M-13094618 CAT 15-A-2006

Ref: C/2022/02

GUPTA CONSULTANTS

Engineers-Architects-Approved Valuers Structural Designers Vaastu Consultants-Interior Designers

Dated: 31.03.2022

STRUCTURAL SAFETY CERTIFICATE

(TO WHOMSOEVER IT MAY CONCERN)

It is hereby certified that all the three buildings of Dayawati Modi Public School, located at Hapur Road, Modinagar, U.P. 201204, satisfy the structural safety requirements as stipulated in the relevant Indian Standard Codes and National Building Code of India and have been constructed following all the guidelines of B.I.S. laid for constructions of high strength load bearing structures.

It is also certified that the buildings are structurally safe.

BUILDING	STORIES	AREA (Sqm)		CLASSROOMS(Nos)
Primary wing	Triple story G+2	2016.00		28
Junior wing	Double story G+1	3840.00		21
Senior wing	Double story G+1	7683.00		30
E		15	Total	79

Date of Inspection: 12.03.2022

Building information schedule enclosed

Applicant:

Manager
Dayawati Modi Public School
Modinagar,
(A Unit of Daya Charitable Trust
New Delhi.)

Structural Engineer:

VIKAS GUPTA
B Tech. (Civil)
IIT-BHU(1993),MIE, F.I.V.

Er. Vikas Gupta B.Tech. (Civil), M.I.E., F.I.V. M-130946-8 F-17437 CAT 15-A-2006 UPOBPAS Reg. No. M1309468/06062018 Structural Designer &

Off: 107-108, Satyam Plaza Complex, P L Sharma Road, Meerut. Ph 0121-4003483 Covt. Approved 9837184019
Resi: C-81, Pallav Puram, Phase I, Meerut. Ph 0121-2577473 E-mail: consultantsgupta@yahoo.co.in

BUILDING INFORMATION SCHEDULE

5	S.	4.2	4.1	4.	3.	2.3	2.2	2.1	2.		
Building Category	Load Bearing Wall Buildings	Type of Foundation	Soil type at sitr (Note 2)	Foundation	Design EQ Factor	Seismic Zone	Importance	Use	Building Function	Building Address	
A (xh < 0.05) B (h = 0.05 to 0.06) C (h = 0.06 to 0.08) D (h = 0.08 to 0.12) E (h > 0.12)	ıgs Yes	Spread Brickwork	Medium		K = 1.0 $I = 1.5$ Alpha $H = 0.05$	IV	1.5	Educational.	Senior Secondary School Building.	Dayawati Modi Public School, Hapur Road, Modinagar UP 201204.	
to 0.12) E(h>0.12)		IS:1893	IS:1904		IS:1893	IS:1893	IS:1893				

5.7	5.6	5.5	5.4	5.3	5.2	5.1	5.
Opening in Walls	Roof covering	Roof Structure	Floors	Mortar (note 4)	Bearing Walls	Building Category	Load Bearing Wall Buildings
Control used on sizes Control used on Location	NA	Flat like floors	R.C.C.Slabs	C:S=1:4	Brick 345 mm / 460 mm thick	A $(xh < 0.05)$ B $(h = 0.05 to 0.06)$ C $(h = 0.06 to 0.08)$	dings Yes
Strengthening around IS:4326						D ($h = 0.08$ to 0.12) E ($h > 0.12$)	

M1309458/05052018 Shuptural Designer & Govt. Ammired Vehiler B.Tech. (Civil), M.I.E., F.I.V. M-130946-8 F-17437 UPCBRAS Rog. No.

5.9 5.8

Vertical Bars **Bands Provided**

At corners of rooms At jambs of openings

Plinth Band

Lintel Band

Yes

Opening in Walls

6. Steel/R.C. frame Buildings

7.6	6.4		6.3	6.2	6.1
Steel Frames	Ductile Detailing of	RC Frames	Ductile Detailing of	Infills/Partitions	Building Shape
Yes/No	Beams	Yes/No	Beams	Out of Plane stability	Both sides symmetri
Yes/No	Columns	Yes/No	Columns	y Check? Yo	cal / One side
Yes/No	Beam column joint	Yes/No	Beam column joint Sheer Walls IS:13920	es/No In Plane stiffnes	Both sides symmetrical / One side symmetrical / Unsymmetrical / Torsion Considered
Yes/No		Yes/No	Sheer Walls	s considered?/	etrical / Torsion
	SPO (6)		IS:13920	Out of Plane stability Check? Yes/No In Plane stiffness considered? /Yes/No IS:1893,IS:4326	1 Considered

The above information is factually correct.

Applicant:

Manager
Dayawati Modi Public School
Modinagar,
(A Unit of Daya Charitable Trust
New Delhi.)

Structural Engineer:

WKAS GOPTA

B Tech. (Civil)

IIT-BHU(1993),MIE, F.I.V.

Er. Vikas Gupta

Er. Vikas Gupta

M-130946-8 F-17437

CAT 15-A-2006
UPOBPAS Reg. No.
W1309463/05062018
M1309463/05062018
Structural Designer &
Govt. Approved Velver